






















ASSEMBLY INSTRUCTION



ΟΔΗΓΙΕΣ ΣΥΝΑΡΜΟΛΟΓΗΣΗΣ

Инструкция за сглобяване




 Ax 40	 Bx 20	 Cx 20	 Dx 4	 Ex 20	 Fx 10
 Gx 60	 Hx 5	 Ix 5	 Jx 5	 Kx 5	 Lx 1
 Mx 1	 Nx 1	 Ox 10	 Px 5	 Qx 1	 Rx 10
 Sx 4					


1




2




3





4





5






6








7




8




x5



9



x5



10

